



The existing fitting on the High Pressure Port is a little esoteric. The existing fitting can make it difficult installing and removing your pressure gauges without refrigerant blowing by. We have found that adding a standard schrader access fitting works well to solve this problem. (a tee style fitting is shown)